




Fig. 1



Stator assembly with
Floating ring and Spacers

Fig. 2





Floating Ring

Fig. 4





FIG. 5 Stator Main body



Flux Plate




Fig. 7a

Return Flux Plate
Inner








Fig 7b


Return Flux plate
Outer



Axial supporting disk

Fig. 8





A-A (2:1)

Floating ring spacer





Fig 9



A-A (2:1)
Stator Spacer




Fig 10




Fig 11




FIG. 12




FIG. 13




FIG.14

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☒ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☒ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.